




1. Forming 2 → Quality: forming and joints require dimensional and surface checks